



SDMS DocID

564984

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION I
JFK Federal Building, Boston, MA 02203-2211

MEMORANDUM

Superfund Records Center
SITE: Pontiac Enterprises
BOOK: 1.3
PAGE: 564984

DATE: April 2, 1991

SUBJ: Screening Site Inspection Review Comments
Pontiac Enterprises LTD
Warwick, RI
TDD No. FI-8901-15
CERCLIS No. RID069857514

FROM: Sharon M. Hayes *SMH*
ME/RI Site Assessment Coordinator

THRU: Don Smith, NUS/FIT RPO *Don Smith*

TO: John Weiss, SSIGL

Pg 1, par 4: Label lot 204 on Figure 2. "A sanitary landfill operation occupied the Pontiac property..."

Pg 1, par 5: The gate described as connecting the Mill complex with the rest of the Pontiac property can not be located on Figure 2.

Pg 6, par 3 + 5: Use either tetrachloroethene or perchloroethene, not both. Also see Pg 7, par 1.

Pg 6, par 6: Concentrations of Aroclor 1254 detected were 420 mg/kg, earlier in the report the units were ppm, be consistent.

EPA concurs with the recommendation for continued investigative work under CERCLA for Pontiac Enterprises LTD.

cc: Carl R. DeLoi, Chief
File